


# Structurally Deficient Bridges on the National Highway System

## 9th Congressional District of Massachusetts, 2003



Structure Number	Road	Location
1 B16003381MUNNBI	HWY ADAMS ST	OVER NEPONSET RIV AT MILT
2 B160094F0MDCNBI	ST 3 CAMBRIDGE ST	.2 MI S OF BLOSSOM ST
3 B160223A3MHDNBI	HWY GRANITE AVE	MILTON TOWN LINE
4 B1603438BMUNNBI	HWY SUMMER ST	1 MI SE OF FT PT CHANNEL
5 B161772KYMHNDNBI	ST 109 SPRING ST	@ DEDHAM TL = D05006
6 B161964F5MDCNBI	HWY MORRISY BLV	.1 MI W OF I 93
7 B162323AWMHNDNBI	I 93 US1 SB OFF R	.25 MI SE OF JCT I93&US1
8 B162323DHMHNDNBI	I 93 BENT 60-56	.2 MI N OF DEWEY SQ TUN
9 B162323DLMHNDNBI	I-93 BT.48-56 N&S	.4 MI N OF DEWEY SQ TUN
10 B162323DPMHNDNBI	I-93 BT.41-48 N&S	.4 MI N OF DEWEY SQ TUN
11 B162323E2MHNDNBI	I 93 NB BNT A3-2	.1 MI S JCT I93&US1
12 C0202635FMHNDNBI	I95 NB & ST128 NB	I95 AT DEDHAM T.L.
13 C0202735GMHNDNBI	I95 SB & ST128 SB	I95 AT DEDHAM T.L.
14 D0503034EMHNDNBI	US 1	.08 KM. NO. OF ST135
15 D0504735MMHNDNBI	I 95 NB & ST128	.51 KM. SE OF US 1
16 D0504735NMHNDNBI	I 95 SB & ST128SB	.51 KM. SE OF US 1
17 M250074UAMBTNBI	HWY ADAMS STREET	S OF LOWER MILLS
18 N250233VVMHNDNBI	HWY PNDRGST C NO	SOUTH BRIDGE
19 N250233VVMHNDNBI	HWY PNDRGST C NO	NORTH BRIDGE
20 W3100535YMHNDNBI	I 95 NB & ST128	.16 KM NW OF CANTON T.L.

Structurally Deficient Bridges

Interstate Highways

Massachusetts District 9

Cities

US Highways

Urbanized Areas

Airports

Amtrak Routes


Park Facilities

Other Rail Lines

Navigable Waterways

Amtrak Stations

Military Bases



The bridges displayed on this map represent the results of a combined BTS/FHWA effort to geocode bridges from the FHWA's 2001 National Bridge Inventory. Of the 6,843 structurally deficient bridges nationwide, 416 could not be geolocated because of insufficient data. Structurally deficient bridges are not necessarily unsafe; all public road bridges receive safety inspections every two years. The bridges listed were categorized as structurally deficient at the time the maps were developed.